


Installing BD600+ USB Driver


Note – this procedure will not work on a normal Windows 10 installation with an unsigned driver.

With the BD600+ powered up and connected to your computer by USB, bring up “Control Panel”, then “Device Manager”.



Look under “Ports (COM & LPT)”. If BD600+ is visible as above, this procedure is unnecessary.


Otherwise, if “BD600+” is not visible, look for “Unknown Device” under “Other Devices.”



Right-click on “Unknown Device” and select “Update Driver Software.”

Installing BD600+ USB Driver

Select “Browse my computer....” You will see the following dialog.



Hit the “Browse” button, and locate and select the CD drive containing the “BD600+ Install Software” CD. Hit “Next”. If you see a “Windows Security” window, click on “Install this driver....”

You should now see a “Windows has successfully updated....” Window. Hit “Close.”