

# Release Notes for BD600+ V2.700

This document covers software version 2.700. It has a number of fixes for problems in the previous version. Small changes have also been made to the User Manual, bringing it to V2.3.

## *General Update Information*

**Eventide recommends that its Broadcast Products are only updated when strictly necessary, as there is a small risk to any update, and it takes time to perform. Read and understand the following Release Notes and only update if you really need the described changes or have or may encounter the problems which it fixes.**

To update the unit, you will need a copy of “217030 Software Installation” – this is a ZIP file, and would usually be downloaded from the Eventide Web Site.

Un-zip the file (“extract all”) and run “bd600\_update.bat”. Follow the instructions on the screen.

**You should normally re-initialize after upgrade (Hold down RAMP\_TO\_ZERO at powerup).**

## Release Notes for *BD600+ V2.700*

### *Problems fixed:*

- *PASS Password* does not work – if set, even if the password key is used as described in the User Manual, *CONFIG* mode cannot be entered. To remove the password, the unit must be re-initialized.
- *Restore Factory Defaults - PANIC button* does not work – it asks you to “RELEASE KEY”, but does not affect settings. *Clear all Memory – RAMP TO ZERO* must be used instead.
- *PULS* only works on BD600E+ and BD600W+, not BD600+.
- *BYP* mode *MUTE* is the same as *RLA* – no mute.
- If an unsuitable *SYNC* source is selected in *CONFIG* mode, there is no unlock display indication until the unit leaves *CONFIG* mode.
- If *SEND* is used, and a USB cable is connected to the BD600+ and a computer, yet no computer application is using the *SEND* data, the BD600+ front panel operations will significantly slow down until either the USB is disconnected or a suitable application is started. Audio is unaffected.

### *Known Issues*

- none

## Release Notes for *BD600+ V2.651*

Original production release.